

INTERNATIONAL




Premix
PREMIX
Windshield washer fluid,
protects up to -20 degrees.
\$3.25/Gallon



Premix
PREMIX55
Windshield washer fluid,
protects up to -20 degrees.
\$150/55 Gallon



Automatic Transmission Fluid
FLTATF668G
TES-668 Allison approved
automatic transmission fluid.
\$30.50/Gallon



Shell Rotella ELC Red
ZSH9404206021G
Extended life coolant/antifreeze for HD
diesel, gas and natural gas power engines.
\$9.50/Gallon



Oil Stabilizer
LP10002
Lucas 100% petroleum product formulated
to eliminate dry starts and reduce friction,
heat and wear in any engine.
\$24.50/Gallon



DEF
FLTFF
Diesel exhaust fluid.
\$10.50
2.5 Gallon



Alternator
8600314
Model 38SI, 12V, pad
mount, 20 output amps,
remote sense terminal,
negative ground.
\$375.00



Transmission Fluid
FLTPS278PKK
PS-278 Eaton automatic
transmission fluid
\$320.00/5 Gallon



Starter
8200433
Model 38MT, 12V, SAE3
mounting, 12 pinion
teeth, insulated, over
crank protection.
\$365.00



Wiper Blades
FLT816-FLT818-FLT820-FLT822-FLT824
Beam, universal mount, constructed
with a single length of spring steel that
applies even pressure across the
length of the blade.
(16,18,20,22, and 24 inch)
\$8.95



Transmission Oil
LP10147
Lucas 50WT trans oil, contains an
exclusive additive concentrate,
long lasting fluid.
\$249.99/5 Gallon



AW Hydraulic Oil
LP10401
AW32 hydraulic oil.
\$72.50/5 Gallon



Synthetic Multi-Vehicle ATF
LP10658
Full synthetic ATF TES295.
\$195.00/5 Gallon



Gear Oil
LP10072
Lucas synthetic SAE
75W90 gear oil.
\$149.99/5 Gallon



CK-4 Diesel Oil
LP10288
Synthetic blend SAE 15W40
HD engine oil CK-4.
\$96.50/5 Gallon



Starter
8200308
Model 38MT, 12V, SAE3
mounting, 11 pinion
teeth, insulated,
over crank protection.
\$365.00



Clutch
C12200235A
Eaton automated HD
ECA w/inertia brake.
\$2,099.00



Battery
31P950
Group 31, 190 reserve
capacity, 950CCA, 12V.
\$112.50/Outright
\$100/Exchange



Brake Shoe Kit
XK2124702QP
Meritor lined shoe kit
with hardware, reman.
\$56.90



Brake Shoe Kit
XK2124707QP
Meritor lined shoe kit
with hardware and
bushings, reman.
\$62.90



Clutch
C30892582
Eaton easy pedal,
15.5"x2", 7 spring,
1700 torq.
\$829.00



Battery
31S925
Group 31, 190 reserve
capacity, 24 month warranty,
950CCA, charging eye.
\$95/Outright
\$82.50/Exchange



Brake Shoe Kit
FLTEN4702QPK
Abex, premium, kit with
hardware, 20,000 lb.
axle rating.
\$36.90



Brake Shoe Kit
XK2124707QPMB
Meritor lined shoe kit
with hardware, no
bushings, reman.
\$59.90



Brake Shoe Kit
FLT4707QP23K
Reman shoe kit, 16.5"
diameter, 7.0" shoe
width, 23,000 axle rating.
\$49.90



Clutch Install Kit
CK3600CL
Eaton clutch install kit
w/input shaft, 2"FR series.
\$219.00

Parts Sale Ends: September 30, 2026



Air Brake Chamber

FLT3030SCB20

Combination chamber, 3030 model, clevis, standard stroke.

\$46.73



Air Brake Chamber

FLTK3030LB24

Piggy back kit, 3030 model, long stroke.

\$49.76



Air Brake Chamber

FLTC30301305

Combination chamber, 3030 model, standard stroke, long rod 13", found on trailer applications.

\$49.99



Air Brake Chamber

FLT3030SB28

Piggy back kit, 3030 model, standard stroke.

\$36.40



Air Brake Chamber

FLT3030LCB20

Combination chamber, 3030 model, Y clevis, long stroke.

\$53.48



Wheel Seal

REVRMT04

Trailer seal, interchanges w/42623, 42627, 3730223, 380065A.

\$26.79



Hood Latch

HLK1022

Fits Prostar LT 4400 Models, International #3544924C2.

\$57.99



Hood Latch

HLK2011

Fits 9200-990 Models, International #1699930C92.

\$19.99



Auxiliary Light

564.55215

Clearance/marker lamp, International #3529900C99.

\$19.99



Wheel Seal

REVRMS01

Steer axle, 12,000 lb. capacity, interchanges w/35066, 35059, 3830236, 380001A.

\$26.79



Wheel Seal

REVRMS05

Steer axle, 16,000 lb. capacity, interchanges w/43764, 43761, 3830264, 380048A.

\$26.79



Wheel Seal

REVRMD02

Drive axle, PTFE lip material, interchanges w/47697, 47691, 3930273, 380003A.

\$26.79



Wheel Seal

REVRMT03

Trailer seal, tapered S, interchanges w/46305, 46300, 3730243, 380025A.

\$26.79



Wheel Seal

REVRMD08

Drive axle, 34,000 lb. capacity, interchanges w/38780, 38776, 3930212, 380023A.

\$26.79



Air Dryer

170.802191

Aftermarket version of Bendix AD-IS.

\$317.99



Air Dryer

BX5010696

Bendix AD-IS.

\$319.99



Air Dryer

BX802191

Bendix AD-IS.

\$725.99



Air Dryer

BX109477

Bendix AD-IP.

\$268.99



Air Dryer

BX801266

Bendix AD-IS.

\$489.99



Air Dryer

BX109685

Bendix remanufactured AD-9.

\$169.99



Air Dryer

170.065612PG

Aftermarket version of Bendix AD-IP with coalescing.

\$219.99



Air Dryer

170.801266PG

Aftermarket version of Bendix AD-IS with coalescing.

\$236.99



Air Dryer

170.065225

Aftermarket version of Bendix AD-9.

\$139.99



Turn Signal Light

564.55218

Side turn signal lamp, International #3889264C92, also available in clear 564.55218CA.

\$29.99



King Pin Kit

ZCPK147E

Stemco no ream QwikKit, 9.05"x1.872", for Spicer/Eaton.

\$489.85



King Pin Kit

ZCPK131R

Stemco no ream kit, B pin type, steering.

\$420.45



King Pin Kit

ZCPK130R

Stemco no ream kit, B pin type, steering.

\$456.75



King Pin Kit

ZCPK120I

Stemco no ream kit, 9.87"x1.921", for Navistar/Spicer.

\$481.35



King Pin Kit

ZCPK103S

Stemco no ream kit, 7.97"x1.359", for Navistar/Spicer.

\$379.15

King Pin Kit

ZCPK102I
Stemco no ream kit, 7.97"x1.359", for Navistar/Thomas.

\$368.85



BRYAN, OH 419-636-1179

bryanparts@selkinginternational.com

STONY RIDGE, OH 419-244-9541

stonyridgeparts@selkinginternational.com

MONROE, MI 734-242-1510

monroe@selkinginternational.com

ELKHART, IN 574-522-2001

elkhartparts@selkinginternational.com

SOUTH BEND, IN 574-289-5531

sbparts@selkinginternational.com

RICHMOND, IN 765-935-4588

richmondparts@selkinginternational.com

GREENSBURG, IN 812-663-7111

greensburgparts@selkinginternational.com

FORT WAYNE, IN 260-482-3000

fwparts@selkinginternational.com

DECATUR, IN 260-724-2166

decaturoparts@selkinginternational.com

LAGRANGE, IN 260-463-3211

lagrange@selkinginternational.com

MUNCIE, IN 765-282-2276

muncieparts@selkinginternational.com